


FIG. 3







FIG. 6








FIG. 7




5/5


FIG. 8



5-11



Attachment #2 - Chub Conveyance



[illegible]

FIG 14

26

267

192


266

268

236

234

232



190

204

206


200

272

209

67

230  
513.15  
228 216 222 224 254 396 392



248 226 246 240 210 249 244 242 236 212 214 66





FIG. 18

192

284



250

252

212

240

278

274

276

280

282

214

FIG. 19




FIG. 20




FIG. 21





Fig. 22

290

296



298

306

292

304

296

340  
340a

16.23

324


298

320

340

326

332



320a

338

336

340b

328

316

330

302


322

334

318

FIG. 24

66



370

FIG. 25





FIG 27



10.26








FIG. 31

76



270

FIG. 32



428

FIG 33





FIG 34






FIG. 34




Fig. 37

450

